Настройка ТСД SEUIC Cruise-1 для чтения кодировок

1. Провести пальцем по экрану снизу вверх и открыть экран со всеми установленными приложениями в ТСД. Открыть приложение Scan tool. В открывшемся приложении Scan tool открыть закладку Barcode



2. В открывшемся списке выбираем пункт UPC/EAN. Проверяем пункты EAN-8 и EAN-13. Оба параметры должны включены – On. Проверяем пункт UPC-A prefixing. Должен быть установлен параметр Add the country code and the system character. Проверяем пункт Quiet Zone должен быть установлен параметр 2.

13:17 💿 🌣 🛄	💿 🖇 🗘 📋 🛛 13:17 💿 🌣 🛄	■ 🕫 🛠 回	Scan tool	:			
Scan tool	Scan tool	:	ver:2.10.12	•			
Scan Barcode	Settings Scan Barco	de Settings	Scan E	Barcode Settings			
			- Transfer UPC-E Ide	ntifying Code: <u>On</u>			
Basic settings	UPC/EAN	TUPC/EAN		I EAN I 3 check send: <u>On</u>			
Code 128	I UPC-A: On		EAN8 check send: <u>On</u>				
DUPC/EAN	I UPC-E: Off		I UPC-A prefixing: <u>Add the country code and the</u> system character				
Code 39	I- UPC-E1: Off						
Code 93	I EAN-8: <u>On</u>		UPC-E prefixing: <u>Do not add</u>				
Cade 11	I– EAN-13: <u>On</u>		UPCE Expanded: <u>Off</u>				
Code II	I- Transfer UPC-A Identify	ing Code: On	UPC-A 2 digit add on: Off				
Interleaved 2 of 5	nterleaved 2 of 5 I– Transfer UPC-E Identifying Cod		I UPC-A 5 digit add on: Off				
🕞 Codabar	- EAN13 check send: On	EAN13 check send: On		I UPC-E 2 digit add on: Off			
NEC 2 of 5	I- EAN8 check send: On	W Ge	LUPC E 5 digit add on: Off				
MSI	UPC-A prefixing: Do not	add		лі. <u>ОП</u>			
	I UPC-E prefixing: Do not	add	EAN I 3 2 digit add on: <u>Off</u>				
► RSS	I- UPCE Expanded: Off	UPCE Expanded: Off		EAN13 5 digit add on: Off			
● QR	I- UPC-A 2 digit add on: O	UPC-A 2 digit add on: Off		EAN8 2 digit add on: Off			
🕞 Data Matrix	- UPC-A 5 digit add on: O	UPC-A 5 digit add on: Off		EAN8 5 digit add on: Off			
China Post	I– UPC-E 2 digit add on: O	<u>ff</u>	Quiet Zone 2				
Adatain 2 of F	I– UPC-E 5 digit add on: O	UPC-E 5 digit add on: Off		I Inverse mode: nolv normal			
Matrix 2 of 5	I- EAN13 2 digit add on: C	- EAN13 2 digit add on: Off		- Decoding rate enhancement: Off			
Composite	I- EAN13 5 digit add on: C	111					

3. В списке находим пункт **QR** и устанавливаем параметры как на рисунке справа.

Scan tool ver:2.10.12		:		Scan to ver:2.10.12	ol	:	
Scan	Barcode	Settings		Scan	Barcode	Settings	
▶ Interleaved 2 of 5			NEC 2 of 5				
Codabar			► MSI				
NEC 2 of 5			▶ RSS				
MSI			🐨 QR				
RSS			I− QR Code: <u>On</u>				
			Minimum length(1~7089): 1				
▶ QR			M	aximum ler	ngth(1~7089): 70	89	
🕟 Data Matrix			I QF	R Inverse:	20		
China Post							
Matrix 2 of 5			I- MicroORInverse On				
			- Quiet Zone:				
PDF417			Data Matrix				
			China Bost				
MicroPDF417							
NaxiCode			Matrix 2 of 5				
Arteo			Composite				
Aztec			PDF417				